


30 29

31 32

1/2" Iron Pipe (DNR Mon.)
(Brass cap missing)
Visited 4/18/2008.

N 88°45'25" W



Property Survey of Johnson Farm as relates to the Thaler Trails

— Trail

LINE TABLE		
LINE	BEARING	LENGTH
L1	N 87°23'31" W	10.31'
L2	S 88°27'32" E	187.80'
L3	N 75°15'28" E	202.80'
L4	N 21°53'28" E	230.20'
L5	N 63°29'29" E	138.00'
L6	N 36°49'30" E	117.00'
L7	N 37°54'30" E	77.00'
L8	N 56°38'27" E	60.30'
L9	S 80°02'30" E	100.00'
L10	N 72°48'28" E	90.00'
L11	S 88°45'25" E	219.11'
L12	S 88°45'25" E	40.82'
L13	S 77°15'31" E	40.00'